SECRET



25X1

25X1

SANITIZED

25X1

PI

1969 DEC 30 18 57 Z

OUT-69 055

S E C R E T 301824Z DEC 69 CITE 7695

SUBJECT: EVALUATION OF MISSION C329C

1. IMAGE QUALITY: THE OVERALL IMAGE QUALITY OF THIS MISSION IS FAIR TO GOOD. THE GOOD QUALITY IMAGERY IS COMPARABLE TO THE GOOD IMAGERY OBTAINED FROM MISSIONS C289C AND 299C. THE FAIR QUALITY IMAGERY IS DUE TO THE PREDOMINANCE, IN SOME AREAS, OF HAZELIKE ATMOSPHERIC CONDITIONS. THE INTERPRETATION SUITABILITY IS FAIR. CLOUD COVER AFFECTS LESS THAN 5 PERCENT OF THE ENTIRE MISSION.

- 2. MISSION DATA:
 - A. C329C
 - B. 10 DEC 1969
 - C. H/002/U2R
 - D. MODE 5, 65-70 DEG LEFT
 - E. T/O: 0040Z, C/ON: 0248Z
 - F. 3400
 - G. 60 IN/SEC
 - H. W-12
 - I. CARD
- . ORIGINAL NEGATIVE:
 - A. EXPOSURE: PROPERLY EXPOSED.
- B. DENSITY AND CONTRAST: GENERALLY MEDIUM WHERE NOT AFFECTED BY DEGRADING ATMOSPHERIC CONDITIONS.
- C. IMAGE DEGRADATION: FOG PATTERNS OF VARIOUS SIZES AND SHAPES ARE PRESENT ON FRAMES 2, 950, 951, 1801, 2243 AND 4504. THESE APPEAR TO BE THE RESULT OF CAMERA OFF/ONS.
- D. PHYSICAL DEGRADATIONS: THREE HEAT SPLICES AND ONE MANUFACTURER'S SPLICE (ULTRA-SONIC) ARE PRESENT ON THIS MISSION.
- E. AUXILIARY DATA: THE IMAGE OF THE SERIAL NUMBER IS OUT OF FOCUS AND UNREADABLE. ALL OTHER SYSTEMS OPERATED SATISFACTORILY
- F. OTHER: THE LAST TITLED FRAME IS 4504.
- 4. POSITIVES: SUITABLE FOR INTERPRETATION PURPOSES. S E C R E T

END OF MESSAGE

CAYOU SEC.

CAYOU

DISTRIBUTION

CX

OFL LUE





6m